

2.3. Cutting With Electric Appliance

Power tools are used to cut pieces in pastel plans. There are models with round and vertical knives, which are used extensively for seat groups. It must be handled carefully and firmly when cutting with power tools.

Drawing extension is required between the patterns. To ensure this, a tolerance gap is left at the joints of the curved and straight lines of the patterns in the pastel plan. This tolerance is left in order to ensure "motion control" of the cutting machine.

This share allows the cutting blade to move smoothly during cutting and prevents cutting defects. The most important factor affecting the movement of the knife is the cutting system preferably used.