

2.2.1. According to technique;

- Frame furniture
- Filled frame furniture

The place of sitting and osculation of sofa or chair which is made furniture frame is measured. The spaces made up massive tree is cut , measured and sticked in accordance to stage of angle combination . If the frame is not covered , the combination can not ve mortising which is combined so that mortising is invisible .



Picture 3.5: Measuring furniture frame and Furniture frame hammered rubbered colon




increased gaps

Picture3.6: Furniture frames

If hardwood is done on the prepared frames or upholstered cushions , the lamp is sticked with plywood in accordance to number of measurement and length by increasing these materials If soft upholstery is done , the process of upholstery is done by hammering rubber and cotton colons on the colon.



Picture 3.7: Seating and back furniture frames proper with general frame



Picture 3.8: Furniture frames hammered zigzag arch



Picture 3.9: Seating and back of furniture frames with cushion upholstery