2.3.1.1 Safety Precautions on Round Blade Cutting Motor

- > The safety shield on the front of the blade during cutting must be lowered to the height of the fabric.
- > Cutting should be done by an expert.
- > The motor cable must not be damaged when cutting.
- > The scissors must be removed in place after the cutting job is finished.