

2.2.3 Cutting Table

Fixed tables are among the most commonly used tables. It consists of wood or laminate coated surfaces on iron feet. The average height is 80-90 cm. Table widths are variable because the fabric width is variable. Since the widths of the fabrics used in the upholstery are between 130-140-150 cm, they are used to cover these dimensions. Table lengths vary according to the conditions of the business. Having a desk provides a comfortable working environment.

The surface property of the table is important for laying and cutting. Therefore, the table surface should not be too slippery or too rough. If it is slippery, it becomes difficult to spread the fabric; if rough, the movement of cutting tools on the table becomes difficult.

Some of the errors made during the cut are very hard to be corrected later, so attention must be taken during the process. The side of the fabric to be cut should be laid on the edge of the cutting table. Fabric width should be 90 degrees. Large pieces should be placed first, and small pieces should be cut in among the large ones.



Resim 2.3 : Table in use to spread and cut the fabric