

1.4.2 To Draw Cloth Spreading (Pastal Drawing)

For sitting groups, the surfaces of the designed models are determined. The stencil is created by including stitch lengths in the pieces. The stitch share can be increased or decreased according to the shape of the piece. This process is repeated one by one for all parts. The shape of the template parts must be stored for a long time without being lost. The most suitable storage environment with the developing technology are the computers. At the same time, the templates are transferred onto cardboard or duralite. In this way, the workshop plan is maintained for use in cloth spreading plan.

Pastal is the block of fabric which is superposed one of the least side of it and spreading over and over with the aim of serial manufacture. In other words; pastal is spreading fabrics in the different shapes according to proper direction of cutting of fabric figure ,pile and features of model to the cutting table .